

NUMBER	ISSUE DATE	REVISION	SUBJECT
818245	1/27/2025	A	Improvement or replacement of Ezy Secure door v1 817002
818145	11/6/2024	A	Alternative Weather Flap
818008	10/7/2024	A	Improving push lock function and Preventing puncture damage on roof
817947	9/13/2024	A	Improvement of push rod assembly P/N 811110
817819	11/19/2024	A	Improving custom seal function
816677	4/10/2024	A	Converting 17000-1() AKE container
816672	4/22/2024	B	Securing AAP door cover with clamp extrusions
816548	2/14/2024	A	Product Improvement - Door Bar Assembly
815965	11/22/2023	B	Replacement of "1 hole" Pull Strap with "2 holes" Pull Strap
815756	10/2/2023	A	Replace parts in door panel assemblies on AAD and AMJ demo containers for
815756	10/2/2023	A	Replace parts in door panel assemblies on AAD and AMJ demo containers
815486	11/7/2024	C	Replacing UOB Panel PN 18255-02 with PN 815313
815466	7/19/2023	A	Converting 126200-1 AKE container
815466	7/19/2023	A	Converting 126200-1 AKE fr 2x bars FD to 3 Velcro Straps FD
815277	6/7/2023	A	Converting of AKE UltraLite container into AKE TwinLite U
815276	7/17/2023	A	One-time repair of pallets from AeroMexico
815195	5/23/2023	A	Remove metal door top middle hinge from AKN container
814261	12/15/2022	B	Double Sided Patching of MacroLite Panels
814238	12/3/2022	A	Rework of net attachment points
813751	7/29/2022	A	Rework of extrusion PN 26222-03
813748	7/22/2022	A	Rework of brackets – conflict with Strap Handle with D-ring
813543	6/8/2022	A	Removal of incorrect logo: "....."
812983	3/10/2022	A	Replace Hinges on Combined Doors
812958	3/11/2022	B	Relocating net straps P/N 801931 of DHL AMJ P/N 33600-1(18)
812935	4/22/2022	A	Conversion from P/N:126200-1(MS) to 126200-1(MS3)
812893	2/25/2022	A	Replace double stud fittings on net on AAY containers
812888	3/11/2022	A	Reinforcement of Fire Resistant Net & Cover Sliding Doors
812850	2/16/2022	A	Change panels from polycarbonate to aluminium, AAY container
812366	11/16/2021	A	Welding guidance for base of RAP container 30850-1(7K)
812150	10/18/2021	A	Cover and Net Interchangeability
811613	7/19/2021	A	Modification from 3 Velcro Straps Fabric Door to Velcro Free Fabric Door
811016	3/25/2022	A	Interchangeability of A-size Base Assemblies
810882	2/28/2022	F	Cargo floor installation on AAY, AAK, AAX, AEP, ABB, LAY containers
810729	2/9/2021	A	Adding milled slot in edge rail for inlay
810650	1/28/2021	A	Interchangeable rubber seals for repair
810590	1/25/2021	A	Attachment of Kick Strip to Twinlite Panels
810305	1/22/2021	A	Relocating holes on door post 809280 & 809281, 37320-1(5X)
810239	11/18/2020	B	Product Improvement- Door Bar Assembly
810049	10/15/2020	A	Door retainer relocation, AMV container 18450-1()
810044	10/15/2020	A	Replacing M6 bolts
809912	9/14/2020	A	Loosening tight AMD QuickZip nets
809905	9/14/2020	A	Remarking Tare Weight on Nordisk Container after Modification
809885	8/31/2020	A	Modification of Strap Handle P/N 808620 to retrofit AAY 126572(KH) & AAX 12
809816	9/1/2020	B	Modification of Strap Handle PN: 808620
809811	8/26/2020	C	Relocate tie down brackets
809687	9/17/2021	B	Replacing spring pins
809623	7/2/2020	A	Replace door lock on Metal Doors
809606	9/16/2024	E	Replacing net and cover on LAY Container, 125853-1(184)
809583	6/9/2020	A	Modification of secondary lock guide tracks

NUMBER ISSUE DATE REVISION SUBJECT

809557	8/20/2020	D	Modification of seal insert
809538	5/27/2020	A	Addition of pull strap to outboard panel on container series 31950-1
809398	3/25/2020	A	Roll-up Door Operation Instructions
809272	9/9/2020	B	Replacing door seal
809219	3/5/2020	A	Changing between QuickZip net and Webbing net on AAY (AAA) containers (L
809216	3/9/2020	A	Replacing base assy
809161	3/2/2020	A	AMJ container front base Ext reinforcement
809129	5/19/2022	E	Replacement of Pull Strap to Double Butterfly Pull Strap
809068	1/18/2021	B	Replacing net and cover on ABU container, 13522-1(184)
809033	2/13/2020	A	Weather flap retainer installation
808976	2/4/2020	A	Reinforcement of AKH Lower Doorpost Brackets to Base
808882	6/30/2022	B	Removal of PKC wings
808787	1/9/2020	A	Tightening Check for CSK Bolt with U-Nut on Lower Base
808690	12/18/2019	A	Retrofit of trail units PN: 127350-1(5X)
808369	11/18/2019	A	Repair of Fabric Cover for Bar Door
808230	11/14/2019	A	Replace Honeycomb LOB 9.0 mm sheet with aluminum 1.0 mm
806906	7/18/2019	C	Replacement of Lower Velcro Strap with Flat Hooks & Tension Buckle
806787	7/5/2019	A	Replacing base assy
806712	6/18/2019	A	Recommended replacement of Fasteners on L/R Door post Gussets
806557	5/16/2019	A	Recommended replacement of Fasteners on Shear Panel
806473	10/23/2023	B	CANCELLED! Adding rivets to secure fiberglass rod in sliding door/net
806285	8/26/2021	E	Adding cutout in edge rail for Sentinel 100 BLE tag
806271	4/8/2019	A	Retrofit DQP Container 19700-1(NH1) to 19700-1(NH)
806234	1/24/2020	B	Replace bar door with fabric door
806101	3/14/2019	A	Pull Strap replacement (P/N 126690-605)
805784	1/25/2019	A	Parts for repair, 12160-1(EK1)
805654	1/10/2019	A	Removable Shelf
805573	12/19/2018	A	Replace vertical door seal on AKE container
805380	11/27/2018	A	Adding vertical single stud straps to 20910-series door
804983	10/18/2018	A	Reinforcement for FR cover door lower edge made from fabric Type 4
804978	10/18/2018	A	Alternative Door Lock Assy for Modified AKH Container
804532	9/13/2018	A	Wording Amendment in Pallet ODLN
804485	9/6/2018	A	Addition of Weather Flap
804484	9/6/2018	A	Addition of Weather Flap
804361	8/21/2018	A	Rework of 18129-04 on container 126572(NC)
804334	8/16/2018	A	Attachment of alum. extrusion "slide in track" reinforcement on roof header be
804158	8/1/2018	A	Retrofit Installation of security bracket in bottom of frame profiles
803769	8/28/2018	B	Replacement of TwinLite 1.1 with TwinLite U 1.1mm
803697	10/25/2018	C	Replacement of "1 hole" pull strap with "2 holes" pull strap
803568	5/8/2018	A	Replace D4000 doors with regular doors.
803494	5/28/2018	B	Improved Adhesion of decals on Nordisk UltraLite & TwinLiteU Containers
803130	3/16/2018	A	Install foldable shelves on container PN 22900-1(JL1)
802950	1/3/2019	B	Installation cam buckle and reinforcement of box stitch
802860	2/1/2018	A	Relocate strap handle brackets on container P/N 510150-1(8Y)
802781	1/17/2018	A	Install External and internal tie down brackets on container PN 13522-1(183)
802465	10/24/2017	A	Shelf Operation backup kit Installation
802424	11/15/2017	A	Change csk bolts on front lower door post brackets on AAX container 127350-
802378	11/7/2017	A	Assembly correction of "Sliding Door assembly, PN 800732"
802352	11/7/2017	A	Move incorrectly fitted seat track bracket from inside to outside,
802239	10/24/2017	A	Install elastic webbing w/double stud and attach hook to door cover assembly
802179	10/20/2017	A	Install webbing w/velcro and connecting bracket for container PN 127350-1(18
802178	10/4/2017	A	Install webbing w/ring and hook on container P/N 13522-1(183)
802170	10/4/2017	B	Install webbing w/ring and hook on container PN 127350-1(185)
201712	8/7/2017	A	Replace of Polycarbonate Panel on Shelf

NUMBER	ISSUE DATE	REVISION	SUBJECT
201711	12/21/2017	C	Patching of Polycarbonate panels
201710	6/9/2017	A	Add "DO NOT CUT" patch to container door
201709	6/2/2017	B	Authorization to transport damaged ULD PN DCT6670-17 AAX/AAD
201708	5/12/2017	A	Cargo floor installation_DCT6670-15&17
201707	5/8/2017	B	Adding shim extrusion underneath door strap brackets
201706	4/19/2017	A	Grind Away Flanges on 126540-357
201705	3/27/2017	A	Relocation of Velcro door straps on doors made of D4000 fabric material
201704	3/27/2017	A	Uses of cover material "type 1" (453) as patching material on "type 2" (430) do
201703	3/13/2017	A	Replacement of rivet attached single web straps with twin-bolted double web st
201702	2/23/2017	C	Heat-Weld patching of damages in TwinLite U body sheets
201701	1/7/2017	A	Replacing pipe W/cam or keeper (Metaldoor assy)
201606	12/5/2016	0	Interchangeable Base Assembly for AKH Container P/N 126540-5(JQ) and P/
201605	11/18/2016	0	Retrofit of Aluminum Roof Panel on AKE
201604	6/16/2017	B	Adding custom seal to Nordisk Velcro strap doors
201603	10/20/2016	B	Adding pullstrap to Outboard side
201602	4/11/2016	C	Reinforcement of forkliftable bases' tine ways
201601	2/23/2016		Modification of 126200-1 AKE containers from bar door to 3 Velcro straps door
201503	6/30/2015	0	Conversion from P/N:126200-2(B65) to 126200-1A06FK
201502	5/5/2015	0	Replacement of Plastic Corner Inserts with Aluminum Corner Casting Inserts
201501	2/27/2015	1	Shelf operation backup kit installation
201408	11/3/2014	0	Fitting PMC Pallet Extension Wing to 96" Edge Rail
201407	9/22/2014		Converting of AKE AluLite container into AKE UltraLite
201406	8/21/2014		Alternative Base Assembly for Modified AMD Container P/N 11240-1(LD1)
201405	7/28/2014	1	Adding bracket for increased racking strength
201404	7/4/2014	1	Retrofitting Aluminium sheets on Weightsaver AKE containers
201403	3/27/2019	B	Rotating AKE bases 180 degrees
201402	3/27/2014	1	Improved Fastening of Bracket on AMX
201401	1/6/2014		Adding velcro along door sides to prevent water entry
201311	12/13/2013		Replacing 60% Roof door with 50% Roof door
201310	11/13/2013		Adding shelves to AKH container P/N 126540-5(JQ)
201309	10/24/2013		Adding door retainer tie down bracket on AAY
201308	7/1/2014	1	Closing door gap on AKE, AKH, DPE and DQF containers
201307	7/15/2013		Modification of AKN containers from metal to fabric door
201306	6/18/2013		Alternative Latch Handle
201305	6/7/2013		Loose nuts on AML containers
201304	5/21/2013		Installation GOH in ALF container
201303	5/9/2013		Alternative Velcro Strap Bracket
201302	3/19/2013	2	Adjustment of AKH Roof door angle in open position
201301	2/21/2013		Correction of typos in manufacturers signs
201205	9/28/2012		Maintaining structural integrity with high tensile fasteners
201204	7/23/2012		Modification of doorposts for AKH Lite container
201203	5/10/2012		Manufacturers Plates for DQF containers P/N 13380-1(PX)
201202	3/30/2012		Adding strength to door bar pin box
201201	1/16/2012	1	Retrofit of Twintex sheets on DKN
201108	12/6/2011		Adding Tie Down Brackets to base front edge stiffener
201107	4/13/2012	3	Edge Rail Solid Cavity Insert
201106	11/10/2011	3	Adding stiffness to M-size base container
201105	12/1/2011	1	Twintex Reinforcement Panel
201104	7/7/2011	1	Heat weld patching of Twintex sheets
201103	6/3/2011		Adding Velcro to reduce door cover gap on AMD
201102	4/26/2011		Adding double stud to reduce door cover gap on AAY
201101	1/12/2012	1	(Obsolete - see SB201103) Use of glued patches on Twintex sheets
201011	12/16/2010		Use of certified containers damaged outside allowable limits
201010	10/18/2010		Installation of Fly Away Kit into AKN container

NUMBER ISSUE DATE REVISION SUBJECT

NUMBER	ISSUE DATE	REVISION	SUBJECT
201009	10/15/2010		Replace TSO Mfg. signs with TSO/ETSO Mfg. Signs
201008	10/12/2010		Replacing clamping extrusion/door with claw extrusion/door
201007	8/18/2010		AMJ(AMH) contour conversion
201006	9/6/2013	1	Adding internal tie down brackets
201005	12/11/2013	2	Replacing blind rivets with Hucklok rivets
201004	2/18/2014	1	Replacing AKE Twintex roof sheet with aluminium
201003	4/20/2010		Adding external tie down bracket on upstanding extrusions
201002	4/19/2010		Modifying 127830 with 1 ea. hex bolt in each corner to 2 ea. hex bolts in each
201001	2/4/2010		Roof load on palletized containers
200905	12/8/2009		Modifying lower door strap attachment on DQF and DPN containers
200904	3/8/2011	1	Interchangeability between QuickZip net and Webbing net on AAY (AAA) cont
200903	1/7/2010	2	Reinforcement of front edge rail on 88"/96"x125" bases
200902	3/13/2014	B	Use of paint / colour
200901	7/5/2009	B	Replace Stud Fitting Pin
200813	2/15/2008	H	Alternate part Nos
200812	12/2/2008		Alternate base for AMA forkliftable/double-base containers
200811	11/4/2008		Permanent attachment of net ring to flat hook
200810	10/2/2008		Use of Door Retainer Velcro
200809	9/19/2008		Damaged/missing internal tie down points / seat tracks
200808	7/9/2008		Installation of rivets in polycarbonate sheets
200807	1/17/2011	2	Use of Cup Washer
200806	6/12/2008		Countersunk holes on bases/pallets
200805	4/1/2008		Removal of sharp edges
200804	4/29/2008	1	Correction of typos in manufacturers plates/signs
200803	2/12/2008		Attachment of cargo to container shell
200802	2/7/2008	1	Use of Nordisk Simi Valley (Telair) parts
200801	1/8/2008	1	Allowable Damage on DKE/DKN and DQF for American Airlines
200708	12/18/2007		Patch material and rivet pitch
200707	1/13/2015	1	Extra customs seal bracket for bifold metal doors
200706	10/15/2007		Cover clamp attachment on tubular containers
200705	6/21/2007		Use of sheet material for bracket P/N 125853-602
200704	8/10/2007	2	Fixing roof door "stiffeners"
200703	3/1/2007		Modification of lower webbing on LBY door nets
200702	2/19/2007		Attachment of door cover on curved containers
200701	1/26/2007		Locking of nut in bolt connections
200610	9/3/2014	2	Loosening Tight QuickZip nets
200609	9/28/2006		Remarking of Tare Weight on PMC pallets
200608	12/9/2015	7	Repair of Door Velcro Straps
200607	9/15/2006		Base sheet splits
200606	7/7/2006		Replacement of door pipe with cams
200605	5/30/2006		Burn rate of fabric doors and door covers
200604	5/9/2006		Manufacturers plates for AKH containers 126540-5(JQ)
200603	4/6/2006		Mistyped information on AMJ Manufacturers plate
200602	2/9/2006		Number of rivet holes in patch
200601	2/13/2006	1	Holes for cover attachment on ALF containers
200509	11/10/2005		Interchangeability of bases 121738 and 122004
200508	11/8/2005		Interchangeability of lower base/front gussets
200507	10/5/2005		Attachment of placard on pallets
200506	9/23/2005		Alternative to strap bracket / bracket attachment
200505	7/25/2005		Allowable damage to Nordisk doors with velcro straps
200504	6/3/2005	1	Webbing for door cover P/N 11462-02
200503	7/1/2008	1	Washers
200502	2/21/2005		Non-certified ULDs
200501	2/18/2005		Base sheet thicknesses

NUMBER ISSUE DATE REVISION SUBJECT

NUMBER	ISSUE DATE	REVISION	SUBJECT
200431	11/25/2004		Cleaning of ULDs
200430	10/13/2021	D	Container patches
200429	11/25/2004		Non-OEM document pouches
200428	11/24/2004		Replacement of cables and modification of cable attachments on AMJ roll-up d
200427	6/6/2017	3	Adding seat track bracket to front base edge rail
200426	11/5/2004		GOH cups in AAP containers
200425	10/26/2004		Replacement of rivet for attaching strap handles
200424	10/22/2004		Conversion of old velcro doors to pocket velcro doors
200423	10/15/2004		AMD base modification
200422	10/11/2004		Modification of cover on AAZ containers
200421	9/22/2004		Shorter doorbeam on AKE containers
200420	9/9/2004	1	Modification of AMA door hinges
200419	8/11/2004		Missing/damaged pallet corners
200418	8/2/2004		Conversion of AKC container to AKE
200417	1/2/2006	1	Interchangeability of doors for AKE containers
200416	9/7/2010	4	Additional/Installation of Pull Straps
200415	5/25/2004		Interchangeability of AAU bases
200414	6/18/2004	1	Allowable holes in vertical flanges of small container bases
200413	5/10/2004	1	Interchangeability of roof panels 122418 and 125151
200412	4/22/2004	1	Attaching door retainer strap to AKH bar door containers
200411	4/1/2004		Reinforcement of AKH container P/N 119622-series
200410	3/29/2004		Replacement of d-rings on Military Platform
200409	11/22/2004	2	Modification of standard AKE container to 60% door on roof
200408	3/23/2004		Allowable holes in vertical flanges of lower deck container bases
200407	3/22/2004	1	Adjusting overall length and width of pallets/container bases
200406	3/15/2004		Modification of aft panel on DQF containers
200405	3/8/2004	1	Securing pallet edge rail corners
200404	2/6/2004		Adding strength to door pin bracket
200403	1/9/2004		Reinforcement of AAF container
200402	1/9/2004		Conversion of bar door to 3-strap velcro door
200401	1/9/2004		Replacement of door lock handles
200318	12/12/2003		Added strength to centre hinge attachment
200317	12/1/2003		Weld cracks in roof panel stiffener and installation of replacement extrusion
200316	11/28/2003		Interchangeability of metal doors
200315	10/2/2003	1	Attachment of door post bracket P/N 115180-329
200314	9/22/2003		Use of 16' pallets in B767F aircraft
200313	9/9/2003		Use of 16" pallets in B767F aircraft
200312	8/21/2003		Modification of AKH lower door Velcro strap
200311	3/10/2010	1	Use of silicone sealant in Nordisk ULD's
200310	8/20/2003		Use of alloys in pallet/base sheets
200309	7/10/2003		Modification of lower door Velcro strap
200308	7/9/2003		Use of preliminary CMM revisions
200307	7/8/2003		Door cover/net interchangeability
200306	9/3/2004	1	Alternate Blind rivet for Threshold
200305	3/8/2010	1	Modification of drain hole configuration
200304	3/19/2003		Minimum pallet dimensions
200303	2/27/2003	1	Alternate parts
200302	3/18/2003	1	Weight, materials and design change in Flight Spares Box
200301	1/3/2003		Use of cargo nets on damaged Nordisk containers
200225	12/19/2002		ECDS Platform - Repair instructions for sheet damages
200224	12/17/2002		Determination of part number
200223	12/12/2002		88" x 125" base interference
200222	5/20/2003	2	Modification of door in DQF container P/N 116624-7
200221	12/9/2005	3	Roll-up Door Modification

NUMBER ISSUE DATE REVISION SUBJECT

NUMBER	ISSUE DATE	REVISION	SUBJECT
200220	10/23/2002		Interchangeability of metal door and shear panels
200219	9/20/2002		Use of blind rivets on Qantas non-welded AKE containers
200218	8/22/2002		Modification of GOH bar attachment
200217	8/13/2002		Strengthening of tubular joints
200216	5/13/2008	4	REPLACED BY SB200204
200215	7/12/2002		Modification of AAP metal door container to net/cover
200214	2/29/2016	4	ULD base/pallet sheet straightening process
200213	10/14/2002	2	Modification of doors in AMA container P/N 115789-1
200212	6/19/2002		Alternative container body sheet alloys
200211	5/31/2002		Modification of DQF 1-bar/1-strap door to 3-strap door
200210	4/30/2002		Modification of AMD sliding door cover and top corner bracket
200209	4/25/2002		Argon gas specification
200208	4/24/2002	1	Torque unit conversion
200207	4/24/2002	2	Use of doors with shorter lower strap
200206	4/8/2008	2	Patching of Heavy Duty Pallet sheets
200205	3/7/2002	A	Strengthening of sheet attachment on 20' and 16' pallets
200204	2/1/2002		Modified shelves P/N 127326
200203	1/31/2002		Modification of AAZ container P/N 123399-1
200202	1/25/2002		Use of base edge rails P/N 115169-754 and 115169-447
200201	1/11/2002		Adjustment of AAN containers
200119	11/18/2004	1	Damaged pull strap assemblies
200118	12/10/2001	1	Adding shelves to P/N 118990-2F_NH
200117	10/17/2001		Use of base edge rails P/N 115169-280 and 115169-411
200116	9/14/2001		Securing of chain splicer nuts
200115	9/13/2001		Modification of front edge on AAP containers
200114	9/3/2001		Broken stitches in AMD net assembly webbing intersections
200113	9/26/2001	1	Modification of aft/base angle bracket
200112	12/18/2001	3	Straightening of 16' and 20' Heavy Duty pallets
200111	5/30/2001		Patching of pallet/container base sheet edge
200110	5/17/2001		Additional rivets for AKE aft panel attachment
200109	5/16/2001		Modification of Britannia AKE containers P/N 116935
200108	2/4/2010	3	Modifying height of AAZ container for New Zealand Post Office
200107	5/14/2001		Welding of metal doors for non-welded containers
200106	5/11/2001		Removal of gap seal bracket
200105	5/10/2001		Interchangeability of polycarbonate and aluminium sheets
200104	3/21/2001		Interchangeability of AKE bases 121799 and 122964
200103	6/6/2001		Attaching door retainer strap to AKH velcro door containers
200102	2/15/2001		Interchangeability of AKE metal door P/N 122128
200101	1/22/2001		Modification of pallet P/N 117545 to 117545-1()
200021	12/10/2000	1	Use of alternate rivets
200020	12/5/2000		Damage limits for Nordisk ULDs
200019	12/4/2000		Revisions to Check and Repair procedures for pallets 113343W-A and -M
200018	11/23/2000	1	Prevention of unauthorized removal of net
200017	11/14/2000		Use of hinges P/N 115169-323 and 113270-332
200016	1/29/2002	2	Use of 88"x125" container base P/N 122227 and 121739
200015	10/25/2000		Use of Tie Down Bracket P/N 115328-323
200014	9/13/2000		Use of AKE bases P/N 123732 and 122964
200013	12/3/2001	2	Welding of containers P/N 125521-, 126200-, 126510, 126520- and 126540-se
200012	8/1/2000		Replacement of 126200-1(BA2) door upper gusset
200011	7/27/2000		Moving front of AAZ container
200010	12/13/2002	1	Interchangeability of base sheets
200009	7/19/2000		Interchangeability of door lock cups
200008	7/7/2000		CX AMA GOH Leg Modification - Trials
200007	6/19/2000		DHL ULD Damage Limits

NUMBER ISSUE DATE REVISION SUBJECT

NUMBER	ISSUE DATE	REVISION	SUBJECT
200006	5/26/2000		Condition inspection of door velcro straps
200005	5/26/2000	1	Update of BA AKE containers P/N 126200-1(BA2)
200004	1/13/2006	1	Use of countersunk bolts with nuts on bases and pallets
200003	4/26/2000		Use of edge rail extrusion on NW AKE bases
200002	4/5/2000		Use of upper door gusset on Northwest AKE containers
200001	12/11/2002	2	Water stains on aluminium sheets or extrusions
199931	1/12/1999		Misspelling of P/N on TSO sign
199930	12/23/1999		Base assembly P/N 126710
199929	12/9/1999		Repair of metal door piano hinge by insert
199928	4/7/2008	1	Attachment of metal Manufacturers Sign / TSO plates
199927	12/13/1999	1	Patching of SQ container bases and pallets
199926	11/5/1999		Attachment of aft/base angle bracket
199925	10/18/1999		Fitting of interchangeable shear panel sheets
199924	10/12/1999		Alternative fasteners for correcting tie down bracket assembly fault
199923	10/5/1999		Allowable size of holes or cuts in panel sheets (DHL)
199922	10/4/1999		Fitting of interchangeable parts for Northwest Airlines
199921	1/11/2000	1	Interchangeable parts for Northwest Airlines
199920	9/7/1999		Velcro door repair limits for Northwest
199919	9/3/1999		Base assembly P/N 121524
199918	9/2/1999		Base sheet P/N 115169-123
199917	3/14/2003	2	Space around base extrusion
199916	7/23/1999		Storage of rubber
199915	6/24/1999	2	P/N 115169-220
199914	5/31/1999		Sheet P/N 115479-102
199913	5/7/1999		Stud fittings on velcro strap doors
199912	3/24/1999		Reinforcement of AMA GOH attachment brackets
199911	3/3/1999		TSO remarking of pallets
199910	3/2/1999		Modification of 16' pallet with core extrusion in 16' direction
199909	2/12/1999	1	Pallet burn rate
199907	2/10/1999		Assembly of upper / lower outboard panels
199906	2/9/1999		Necessity of straightening extrusions
199905	5/13/2008	2	REPLACED BY SB200101/SB200404
199904	12/19/2001	2	Use of assembly fasteners
199903	1/27/2009	1	Handling of ULDs
199902	3/25/1999	1	Repair/reinforcement of riveting on Nordisk 20 ft. pallet P/N 125954-G
199901	1/8/1999		Replacement of sign plates
9826	12/9/1998		Bolt with ring and self locking nut
9825	11/23/1998		Doors with fixed pins on Qantas DQF containers
9824	11/13/1998		Specification of Nordisk bolts, nuts and washers
9823	11/12/1998		Use of no. 8 lock bolt
9822	1/12/2001	1	Alternative P/N for base pods
9821	10/21/1998		Removal of cross cables
9820	10/20/1998		Looped door cross cables
9819	5/8/2003	1	Welding rods
9818	6/9/2004	3	Replacement of pull-straps on air cargo containers
9817	7/31/1998	1	Cover cables on AAZ and AAK container
199816	6/3/2008	1	Weld repair by inserting extrusion on welded containers
9815	8/18/1998	2	Replacement of metal door with net and cover
9814	12/13/1999	1	Retrofitting aft panel (P/N 123306) on LD3 with two metal doors
9813	11/30/1998	1	Red equivalent to blue net and covers
9812	4/16/1998		Use of bases on Singapore Airlines AKC containers
9811	3/23/1998		Holes in door post for "Security board"
9810	3/2/1998		Weld on container base edge rail flanges
9809	2/24/1998		Change of part number for double stud fitting

NUMBER ISSUE DATE REVISION SUBJECT

9808	2/17/1998		Change of sign number
9807	2/12/1998		Hinge moved on pallet wings P/N 117422-4
9806	1/30/1998		Explanatory notes to CMM No. 25-51-22
9805	1/29/1998		Explanatory notes to CMM No. 25-52-26
9804	1/16/1998		Strengthening of sheet-to-extrusion attachment in Nordisk containers
9803	1/14/1998		Reinforcement of edge rails on Nordisk pallet P/N 121650-series
9802	1/13/1998		Permanent attachment of nets to Nordisk pallets
9801	1/9/1998		Modification of blind rivet P/N 113270-307
9715	12/12/1997		ULD Burn rate
9714	12/15/1997		Interchangeability and commonality of Nordisk container parts
9713	12/11/1997		Special repair of Nordisk 20ft pallet P/N 122430-G, serial number PGE7023KZ
9712	8/15/1997		Magna-Grip bolts and collars
9711	5/27/1997		Correction of LD-3F (DKN) base hole to avoid conflict w/shear panel bracket
199710	5/16/1997		Repair of cover
9709	2/28/1997		Nordisk oversized 20ft and 16ft pallets
9708	12/11/1997		Change of P/N on LD8 metal door
9707	12/10/1997		ULD CMM Repair fasteners
9706	10/13/1997		Service Letters / Service Bulletins
9705	10/10/1997		LD2 and LD3 door cross cables
9704	9/29/1997		Repair of loose leg on pallet wing
9703	7/9/1997		Use of extrusion 5120
9702	7/10/1997		Nordisk and Frigotainer base sheet part numbers
9701	1/15/1997		Aft panel stiffeners
199603	11/7/1996		Repair of 20' pallets seat track lips
9602	11/18/1996		Approval of Northwest Estex door
9601	5/31/1996		Door nets with double stud fittings
9403	9/8/1994		Patching rivets
9402	8/1/1994		Issue, re-issue and revising procedures for the CMMs made by NAP
9401	7/25/1994		Change of part number system
9301	1/1/1993		Change in vendor's rivet part numbers